


## DP318

PROPRIETARY AND CONFIDENTIAL.  
ALL DIMENSIONS HAVE A +/- 1/32" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

### SPECIFICATIONS

- Additional mounting screw lengths available upon request.

### TABLE OF CONTENTS





..... 1X DP318




..... 2X  
1" M4 X 0.70 Thread  
Mounting Screw

	(A) LENGTH	(B) C.T.C.
DP318A	222.00mm (8-3/4")	159.50mm (6-9/32")
DP318B	329.00mm (12-15/16")	255.50mm (10-1/16")



Determine the position and location of the part on the work surface. Mark the mounting positions and drill the hole for the mounting hardware.



Use (2) 1" M4 X 0.70 thread mounting screw to secure the part to the work surface. Make sure the part is fully level on the work surface.