MOCKETT
DESIGN • QUALITY • SERVICE

310.318.2491
800.523.1269
www.mockett.com

# DP434 Series


PROPRIETARY AND CONFIDENTIAL. All dimensions have a (+/-) 1/32" tolerance unless otherwise specified. We do not recommend drilling or cutting any holes before receiving a product or a product sample.

## SPECIFICATIONS

- M4 X 0.70 thread mounting holes.
- Additional mounting screw lengths available upon request.

| | (A)<br>LENGTH | (B)<br>C.T.C. |
|---|---|---|
| DP434A | 5-21/32"<br>(144.00mm) | 5-1/32"<br>(128.00mm) |
| DP434B | 8-3/16"<br>(208.00mm) | 7-9/16"<br>(192.00mm) |
| DP434C | 10-23/32"<br>(272.00mm) | 10-3/32"<br>(256.00mm) |


## TABLE OF CONTENTS




. . . . . 1X DP434 Series




. . . . . 2X M4 X 0.70 X 25.00mm
Pan-head Machine Screw







REAR VIEW





RIGHT VIEW

## 1




Determine the position and location of the part on the work surface. Mark the mounting positions and drill the holes for the mounting hardware.

## 2




SIDE VIEW

Use (2) M4 X 0.70 X 25.00mm pan-head machine screws to secure the part to the work surface. Make sure the part is fully level onto the work surface.