MOCKETT
DESIGN • QUALITY • SERVICE

310.318.2491
800.523.1269
www.mockett.com

DP435 Series


PROPRIETARY AND CONFIDENTIAL. All dimensions have a (+/-) 1/32″ tolerance unless otherwise specified. We do not recommend drilling or cutting any holes before receiving a product or a product sample.

SPECIFICATIONS

- M4 X 0.70 thread mounting holes.
- Additional mounting screw lengths available upon request.

	(A) LENGTH	(B) C.T.C.
DP435A	6-15/16″ (176.00mm)	6-5/16″ (160.00mm)
DP435B	13-7/32″ (336.00mm)	12-19/32″ (320.00mm)


TABLE OF CONTENTS




. . . . . 1X DP435 Series




. . . . . 2X M4 X 0.70 X 25.00mm Pan-head Machine Screw






REAR VIEW




RIGHT VIEW

1



Determine the position and location of the part on the work surface. Mark the mounting positions and drill the holes for the mounting hardware.

2



SIDE VIEW

Use (2) M4 X 0.70 X 25.00mm pan-head machine screws to secure the part to the work surface. Make sure the part is fully level onto the work surface.