MOCKETT
DESIGN • QUALITY • SERVICE
310.318.2491
800.523.1269
www.mockett.com


# DP437

PROPRIETARY AND CONFIDENTIAL. All dimensions have a (+/-) 1/32″ tolerance unless otherwise specified. We do not recommend drilling or cutting any holes before receiving a product or a product sample.

## SPECIFICATIONS

- M4 X 0.70 thread mounting holes.
- Additional mounting screw lengths available upon request.


## TABLE OF CONTENTS




. . . . . 1X DP437




. . . . . 2X M4 X 0.70 X 25.00mm
Pan Head Machine Screw







TOP VIEW





REAR VIEW

## 1




Determine the position and location of the part on the work surface. Mark the mounting positions and drill the hole for the mounting hardware.

## 2




SIDE VIEW

Use (2) M4 X 0.70 X 25.00mm pan-head machine screw to secure the part to the work surface. Make sure the part is fully level onto the work surface.