MOCKETT

DOUG MOCKETT & COMPANY, INC.

310.318.2491 • 800.523.1269 • www.mockett.com

PCS49E/UC2

PROPRIETARY AND CONFIDENTIAL.
ALL DIMENSIONS HAVE A +/- 1/16" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

⚠ WARNING ⚠

- For indoor use only.
- For use on a normally dry work surface.
- If any malfunction occurs, do not attempt to disassemble or repair.
- Avoid placing the unit in a high temperature environment or near fire.
- Avoid liquid spills into outlet.
- Do not insert foreign objects into the socket.
- Allow enough clearance for part operation.

SPECIFICATIONS

- 6 ft. cord length.
- Table thickness is 3/4" MIN. to 1-3/4" MAX.
- Plug dimension is 1-11/32" X 1-1/32" X 7/8".
- USB-A and USB-C ports are for charging use only.

TABLE OF CONTENTS

 1X PCS49E/UC2

. . . . . 2X Thumb Screw

. . . . . 2X Wing Clamp

. . . . . 1X Wire Manager





FRONT VIEW



SIDE VIEW

1



Determine the position and location of the unit in the work surface. Cut the hole at 2" X 6-3/4". Place and allow enough clearance for unit operation. DO NOT place unit where the cables are strained or trapped.

2



Guide the power cord through the cutout. Install the unit into the cutout and make sure it is fully leveled onto the surface.

PROPRIETARY AND CONFIDENTIAL.
ALL DIMENSIONS HAVE A +/- 1/16" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

3



Slide the (2) wing clamps in the underside track of the unit.

4



Use (2) thumb screws to secure the part in the work surface. Plug the unit into a nearby outlet and unit is ready for use.

5



Affix optional wire manager under desk for cable management.