




NOTE:

- 6 ft. cord length.
- Table thickness is 1/2" MIN. to 1-3/4" MAX.
- Plug dimension is 1-11/32" X 1-1/32" X 7/8".




FRONT VIEW

1




Determine the position and location of the unit on the work surface. Make a 3" diameter hole cut out. Place near a power outlet and allow enough clearance for unit operation. DO NOT place unit where the cable is strained or trapped.

2




Guide the power cord through the cut out. Install the unit into the cut out and make sure it is fully leveled onto the surface.

3




Guide the threaded lock ring through the power cord. Install the lock ring onto the mounting collar by turning clockwise. Locking ring should rotate smoothly if properly engaged. If not, the locking ring may be cross-threaded - undo and try again.

TABLE OF CONTENTS:



.....1X PCS74



.....1X Lock ring