

DP323


PROPRIETARY AND CONFIDENTIAL.
ALL DIMENSIONS HAVE A +/- 1/32" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

SPECIFICATIONS

- Additional mounting screw lengths available upon request.

	(A) LENGTH	(B) C.T.C.
DP323A	1-17/32" (38.50mm)	N/A
DP323B	9-27/32" (250.00mm)	6-5/16" (160.00mm)
DP323C	16-5/32" (410.00mm)	12-19/32" (320.00mm)



TABLE OF CONTENTS




..... 1X DP323



... (1X) DP323A / (2X) DP323B & C
1" M4 X 0.70 Thread
Mounting Screw




REAR VIEW




RIGHT VIEW

1



Determine the position and location of the part on the work surface. Mark the mounting positions and drill the hole(s) for the mounting hardware.

2



Use provided 1" M4 X 0.70 thread mounting screw(s) to secure the part to the work surface. Make sure the part is fully level on the work surface.