


## DP430 Series

PROPRIETARY AND CONFIDENTIAL.  
ALL DIMENSIONS HAVE A +/- 1/32" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

### SPECIFICATIONS

- M4 X 0.70 thread mounting holes.
- Part is handmade and slight variation in textures and color may occur.
- Additional mounting screws lengths available upon request.

### TABLE OF CONTENTS





..... 1X DP430




..... 2X 1" M4 X 0.70 Thread Mounting Screw

	(A) LENGTH	(B) CENTER TO CENTER
DP430A	3-25/32" (96.00mm)	2-17/32" (64.00mm)
DP430B	5-1/32" (128.00mm)	3-25/32" (96.00mm)
DP430C	6-5/16" (160.00mm)	5-1/32" (128.00mm)




REAR VIEW




RIGHT VIEW

1



Determine the position and location of the part on the work surface. Mark the mounting positions and drill the holes for the mounting hardware.

2



Use (2) 1" M4 X 0.70 thread mounting screws to secure the part to the work surface. Make sure the part is fully level on the work surface.