

PCS141

PROPRIETARY AND CONFIDENTIAL.
ALL DIMENSIONS HAVE A +/- 1/32" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.




WARNING

- For indoor use only.
- For use on a normally dry work surface.
- If any malfunction occurs, do not attempt to disassemble or repair.
- Avoid placing the charger in a high temperature environment or near fire.
- Allow enough clearance for part operation.
- Do not insert foreign objects into the socket.
- Avoid liquid spills into outlet.

SPECIFICATIONS

- 6 ft. cord length.
- USB-A and USB-C ports are for charging use only.
- Recommended cutout is 2-1/2" DIA. (63.50mm).
- Recommended table thickness is 25/32" (20.00mm) MIN. to 2-5/32" (55.00mm) MAX.
- Minimum clearance required from the edge of the work surface is 25/32" (20.00mm).


TABLE OF CONTENTS




..... 1X PCS141



..... 1X Lock Ring




TOP VIEW




FRONT VIEW

1



Make a cutout in the desired location on your work surface. Allow enough clearance for unit operation. DO NOT place unit where cable is strained or trapped. (Note: Minimum clearance required from the edge of the work surface is 25/32" (20.00mm).)

2




Install the PCS141 into the cutout and make sure it is fully leveled onto the work surface.

PCS141


PROPRIETARY AND CONFIDENTIAL.
ALL DIMENSIONS HAVE A +/- 1/32" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

3



Guide the cable through the lock ring and secure the unit by turning the lock ring clockwise. Plug the power cord into a nearby outlet and the unit is ready for use.

4



Slide PCS141 cover to expose outlet and USB ports.