

## PCS90/UC-U

PROPRIETARY AND CONFIDENTIAL.  
ALL DIMENSIONS HAVE A +/- 1/16" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.


### ⚠ WARNING ⚠

- For indoor use only.
- Not recommended for use on wet surfaces.
- If any malfunction occurs, do not attempt to disassemble or repair.
- Allow enough clearance for part operation.
- Avoid liquid spills into outlet.
- Do not insert foreign objects into the socket.
- Avoid placing the unit in a high temperature environment or near fire.

### SPECIFICATIONS

- 6 ft. cord length.
- USB-A and USB-C ports are for charging use only.
- Recommended cutout is 9-1/8" X 4-3/4".
- Recommended table thickness should be 3/4" MIN. to 2" MAX.

### TABLE OF CONTENTS





..... 1X PCS90/UC-U




..... 2X Mounting Bracket




..... 4X 2" Spade Head 10-32 Thread Thumb Screw




FRONT VIEW



RIGHT VIEW



Determine the position and location of the unit on the work surface. Make a cutout in the desired location on your work surface. Place and allow enough clearance for unit operation. DO NOT place unit where the cables are strained or trapped.




Guide the power cord through the cutout. Install the unit into the cutout and make sure it is fully leveled onto the work surface.

## PCS90/UC-U


PROPRIETARY AND CONFIDENTIAL.  
ALL DIMENSIONS HAVE A +/- 1/16" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

### 3




Use the appropriate key slots on the mounting bracket.

### 5



Use (4) 2" spade head 10-32 thread thumb screws to secure the part in the work surface. Plug into nearby outlet and unit is ready for use.

### 4



Align the (2) mounting bracket to the desired key slots to the T-studs on both sides under the unit.