


PART #


DP224

310.318.2491 • 800.523.1269 • www.mockett.com



RIGHT VIEW


1



Determine the position and location of the unit to install flush on the work surface.

NOTE:
A CNC machine is recommended to accommodate part installation.


2



FRONT

Determine the front of the work surface. Input the values into the CNC machine.

3



Install the DP224 into the cut out and be sure it is fully level on the surface. (Note: Adhesive is optional and not included.)