




Determine the position and location of the unit on the work surface. Cut the hole at 4-1/2" X 2".



Install PCS62A/R into the cut out and be sure it is fully level on the surface.






Use (2) Brackets and (2) Thumbscrews below the PCS62A/R to secure unit onto the surface.



Plug the unit into nearby outlet (outlet should be close enough to where power cord is not taut or strained) and unit is ready for use.

TABLE OF CONTENTS:

1 X PCS62A/R
2 X BRACKET
2 X THUMBSCREW