


NOTE:

- 6 ft. cord length.
- For use on a normally dry work surface.
- Table thickness is 5/16" MIN. to 1-7/16" MAX.
- Plug dimension is 1-11/32" X 1-1/32" X 7/8".

TOP VIEW


FRONT VIEW

1




Determine the position and location of the unit in the work surface and make the cut out. Allow enough clearance for unit operation. DO NOT place unit where cable is strained or trapped.

2




Guide the power cord through the cut out. Install the unit into the cut out and make sure it is fully leveled onto the work surface.

3



Tighten the lock ring until the unit is secure. Plug cord into a nearby outlet and the unit is ready for use.

TABLE OF CONTENTS:



..... 1X PCS75



..... 1X Lock ring