



Make sure the unit is fully leveled the on the work surface. Secure the unit by tightening thumb screw. Plug the unit into nearby outlet (outlet should be close enough to where power cord is not taut or strained) and unit is ready for use.

