




1A INSTALLATION OPTION A: SURFACE MOUNT




Determine your mounting location and DRILL/CNC a 1-3/4" DIA. hole.




Make sure the surface is clean, add adhesive (OPTIONAL) and insert part.



1B INSTALLATION OPTION B: FLUSH MOUNT



Determine your mounting location and with a template (NOT INCLUDED) ROUTE/CNC a 2" DIA. at 1/8" deep.



Then DRILL/CNC a hole at 1-3/4" DIA. Make sure the surface is clean, add adhesive (OPTIONAL) and insert part.




TABLE OF CONTENTS:



..... 1X SS3 CAP



..... 1X SS3 SLEEVE