



1A

INSTALLATION OPTION A: SURFACE MOUNT




Determine your mounting location and DRILL/CNC a 2-3/4" DIA. hole.

2A




Make sure the surface is clean, add adhesive (OPTIONAL) and insert part.

3A




1B

INSTALLATION OPTION B: FLUSH MOUNT



Determine your mounting location and with a template (NOT INCLUDED) ROUTE/CNC a 3" DIA. at 1/8" deep.

2B



Then DRILL/CNC a hole at 2-3/4" DIA. Make sure the surface is clean, add adhesive (OPTIONAL) and insert part.

3B




TABLE OF CONTENTS:



..... 1X SS3A
CAP



..... 1X SS3A
SLEEVE