



NOTE:


- 4 ft. Cord
- USB ports are for charging use ONLY.
- For use on a normally dry work surface.
- Power adapter is 3-1/16" X 1-11/16" X 1-7/16".




RIGHT VIEW

1

Work surface
(Not Included)



2




Pan-head screws

Determine the position and location of the unit under the work surface. Place and allow enough clearance for unit operation. DO NOT place unit where the cable is strained or trapped.



Secure the unit by using (2) pan head wood screws. Make sure the unit is fully leveled under the work surface.

3



Connect the power adapter plug into the rear of the unit. Plug the power adapter unit into nearby outlet. The indicator light will light up when the unit is powered, and will get brighter once the unit is in use.

TABLE OF CONTENTS:

1X UCS3
1X Power Adapter
2X 3/4" No. 10 Pan-head screws