



1



Determine location for WM43.

2



Lift cables and place WM43 against the wall.
Place cables inside wire manager.