


SIGN5



PROPRIETARY AND CONFIDENTIAL.
ALL DIMENSIONS HAVE A +/- 1/32" TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DO NOT RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.

TABLE OF CONTENTS




..... 1X SIGN5

	(A) LENGTH
SIGN5A	8"
SIGN5B	10"




FRONT VIEW




SIDE VIEW

1



Determine the position and location of the part on your work surface.

2



Slide a sign into SIGN5 from either side.