

1. Remove mounting bracket from PCS40/5 by removing plastic thumb nut.
2. Install unit into table cut out as shown and reinstall mounting bracket and plastic thumb nut tighten as required. (NOTE: Recommended surface thickness 3/4" to 1-1/2" thick.)
3. Connect data jack as needed.

