MOCKETT

PART #

PCS49A-U

310.318.2491 • 800.523.1269 • www.mockett.com






Table thickness is 3/4 " MIN. to 1-3/4 " MAX.

2




Drop the unit into the cut out. Make sure the unit is fully leveled into the work surface.

1



Determine the position and location of the unit on the work surface. Cut the hole at 6-3/4 " X 2".


3




Slide the wing clamps in the underside track of the unit. Use (2) thumb screws secure the part in the work surface.



PLEASE USE APPLICABLE ADAPTER FROM DATA TREE. (SEE PCS DATA TREE PAGE FOR MORE INFORMATION.)






PART #

PCS Data Tree


310.318.2491 • 800.523.1269 • www.mockett.com

1.) Select the appropriate adapter from the chart below. (example: Panduit Mini-Com Series jack would use "FFF" adapter marked on back of adapter.)





- 2.) Snap Jack into adapter following the instructions provided with the jack.
- 3.) Once assembled, snap adapter into the notched, square holes in the orientation shown.



NOTE:

Please verify fit of jack in adapter before ordering large quantities as manufacturer designs may change without notice.