




**NOTE:**

- 6 ft. cord length.
- For use on a normally dry work surface.
- Plug dimension is 1-11/32" X 1-1/32" X 7/8".
- USB-A ports are for charging use only.
- Table thickness is 1/4" MIN. to 1-1/2" MAX.




**SIDE VIEW**

**1**




Determine the position and location of the unit on the work surface. Allow enough clearance for unit operation. DO NOT place unit where the cable is strained or trapped.

**2**



Remove lock ring from unit. Guide the power cord through the cut out. Install the unit into the cut out and make sure it is fully leveled onto the surface.

**3**




Guide the lock ring through the power cord. Secure the unit by turning the lock ring clockwise.

**TABLE OF CONTENTS:**


	..... 1X PCS67G/2/U2
	..... 1X Lock Ring
	..... 2X Top
	..... 6X Snap-in Adhesive Pad
	..... 1X Wire Manager

4




Align the snap-in adhesive pads to the top of the unit.

5




Peel off the adhesive backing on all six snap-in adhesive pads.

6



Align the top to the unit. Make sure it is fully leveled onto the top surface. Plug the unit into a nearby outlet and unit is ready for use.

7



Optional wire manager.