



NOTE:

- 6 ft. cord.
- Mobile device must be wireless charging ready. Check mobile manufacturer for compatibility.
- Table thickness is 3/4" Min. for surface mount installation.
- Wireless output is 10W.
- Power adapter is 1-29/32" X 1-27/32" X 15/16".




1a Table Top




Place the unit on the desired location of the work surface. Make sure the unit is fully leveled on the work surface.

2a





Plug cord into power outlet using the power adapter. The indicator light will turn on and the unit is now ready for use.

3a




Position the mobile device on the center of the charging area. The charging icon will activate on the device's screen when properly aligned at the center of the charging area.

TABLE OF CONTENTS:

 1X WCS9
 1X Power Adapter


1b Surface Mount

58.50mm DIA.
(2-5/16")
CUT OUT




Determine the position and location of the wireless charger on the work surface. Cut the hole at 58.50mm DIA (2-5/16"). (Note: We do not recommend cutting before receiving product.)

2b



Press fit the unit into the cut out and make sure the unit is fully leveled on the work surface. Plug into power outlet using the power adapter. The indicator light will turn on and the unit is now ready for use.

3b



Position the mobile device on the center of the charging area. The charging icon will activate on the device's screen when properly aligned at the center of the charging area.